

## CRUISER VIEWFINDER SIGNATURE LP COMPARTMENT REPAIR 11041R

The following steps are to ensure that the LP compartment is completely secured, as well as sealed off from the interior of the coach.



- 1.) The galvanized LP container must be securely fastened to the bed framework. The picture above shows one that has not been secured.




- 2.) This can easily be done with 3-4 sheet metal, or any wood screw. The intent is to merely keep the box from moving or shifting while the trailer is in transit.

## CRUISER VIEWFINDER SIGNATURE LP COMPARTMENT REPAIR 11041R




3.) Shown above is the compartment now securely fastened. We can now address sealing this compartment.



4.) If smaller gaps exist, they can be sealed with any commercial waterproof type sealant or caulk. If slightly larger openings are evident, they can be addressed and sealed with spray foam. It is imperative to ensure there are no gaps or voids in the sealant.



## CRUISER VIEWFINDER SIGNATURE LP COMPARTMENT REPAIR 11041R



5.) All joints between galvanized LP compartment and sidewall of unit need to be sealed.



In addition, all joints within the compartment itself should be sealed to ensure no LP can escape into the interior of the coach.